



Assembly of a Zelup[®] Gun through a wall or a partition

Warning: The connection box must be attached to a surface perpendicular to the wall to ensure that the hose is not bent (see diagram)



1. Drill an over 27 mm hole into the wall in order to let the hose with its anti-kink spring pass through it.



2. Pass the tubes through the connection box bore and through the tightening nut.



3. Connect the transparent air input tube to the aluminum connection 1/4 F" BSP on the box (see picture).



4. Connect the blue water input to the water connection 3/4 M" BSP on the box (see picture).



5. Slide the tightening nut along the tubes and screw it in the screw head of the anti-kink spring.



6. Your connection box is now ready for use. You can now connect it to your compressor and water source.

